





BENCH INSTRUCTIONS **KBC1640**














1-1/2" x 1/4" Lag screw P/N HLAG025C150188



5/16" WASHER P/N WUSS031WAS188



5/16" Hex nut P/N NNYL031CNUT188



#12 X 2" Flathead screw P/N DSSF012C200188

REQUIRED TOOLS (NOT INCLUDED)

- 1 #3 SQUARE BIT
- 7/16 WRENCH
- 1/2 WRENCH
- 1 POWER DRILL
- 1/8" DRILL BIT
- 1 T30 TORX BIT IS INCLUDED

NOTE: IT IS IMPORTANT TO KEEP ALL BOLTS FINGER TIGHT **DURING ASSEMBLY UNTIL ENTIRE UNIT IS ASSEMBLED**


> **HARDWARE & TOOLS REQUIRED FOR ASSEMBLY**

2/4

BENCH INSTRUCTIONS KBC1640

STEP 1

- Stand the plastic bench ends (A) upright
- Place the support braces (B) into the plastic bench ends (A) as shown
- Make sure to align the holes of the support braces with the hole in the plastic bench end
- Secure with 1-1/4" x 1/4" lag screws (D) in the outer bench ends
- In the center bench end (A), secure with (2) #12 x 2-1/2" flat head screws (H)




Step 2

Place a plastic board (C) over the plastic end supports (A)

Align the holes of the plastic board (C) with the holes

in the support braces (B) Secure with (4) 3" x 5/16" carriage bolts (F), 5/16" washers (J) and 5/16" hex nuts (G)

Secure the center bench end (A) with (1) round head lag screw (E) through the top of plastic board (C) Use supplied T-30 torx bit



SEAT ASSEMBLY

3/4

